

SCHLEIFRING

AUTOMATION

STRESSOMETER

Slip ring for high temperature + high speed demands

- 57 ways slip ring for stressometer shaft
- Signal transmission by integrated electronics
- High temperature environment
- Speed up to 6000 min⁻¹

